

Restoration at Southampton's Old Burying Ground,
Southampton Sept 25th – Oct 4, 2015

#703- ELIZABETH HERRICK d. 1884

9/25/2015: CONCRETE CUT FROM PEDESTAL

9/26/2015: HEADSTONE RAISED AND SET

9/27/2015: MORTAR ADDED TO HEADSTONE

JOEL SNODGRASS, ZACK STUDENROTH, CHRIS
ROBINSON, D. DELANEY



Condition
in 2006
U of Penna



#706 – Martha Herrick, D. 1819

9/24/15: The Headstone was straightened



Condition
in 2006
U of Penna



#707 – Micaiah Herrick D. 1781

9/24/2015: Headstone was straightened

Condition in
2006

U of Penna



#708 - MRS. ABIGALE HERRICK D. 1795



10/4/2014: HEADSTONE SEPARATING; LIQUID GROUT INJECTED INTO FRONT OF THE HEADSTONE. JOEL SNODGRASS, ZACK STUDENROTH, CHRIS ROBINSON AND DENNIS DELANEY PRESENT.

9/24/2015: HEADSTONE & FOOTSTONE STRAIGHTENED.



Condition in
2006
U of Penna



#713 GEORGE HERRICK D. 1873

9/25/2015: CONCRETE CUT FROM AROUND THE PEDESTAL

9/26/2015: HEADSTONE BROKEN AT MID SECTION; EPOXY REPAIR AND RESET INTO PEDESTAL.

9/27/2015: DECORATIVE MORTAR ADDED TO BREAK LINES.



Condition
in 2006
U of Penna

#714 CHARLOTTE HERRICK D. 1897

9/25/2015: EPOXY REPAIR OF BOTTOM OF
HEADSTONE PEDESTAL.

9/26/2015: BROKEN MID-SECTION WAS EPOXY
REPAIRED AND RESET TO BOTTOM SECTION.

9/27/2015: DECORATIVE MORTAR ADDED TO
BREAK LINES.

Condition in
2006
U of Penna



#715 – MRS. ABIGALE ROGERS D. 1782

9/25/2015: CONCRETE REMOVED FROM AROUND THE BOTTOM OF THE HEADSTONE. THE HEADSTONE IS IN BAD CONDITION WITH INSCRIPTION WORN AWAY. MUCH OF IT IS MISSING.

DISCOVERED A LARGE SECTION OF A BROWN STONE UNDERGROUND; IT WAS LATER DETERMINED TO BE FOR THE HEADSTONE OF MR. ROGERS. THE PIECE WAS SET INTO THE EARTH AT THE REAR OF HIS HEADSTONE.



Condition in
2006
U of Penna

